

Fig. 1




Fig. 2 A





Fig. 2 B



3/8

Fig. 3




Fig. 4 A





Fig. 4 B



5/8

Fig. 5 A




Fig. 5 B





Fig. 6 A

DIRECTLY AFTER FILM FORMATION

PROTRUSION

DEPRESSION



SUBSTRATE

LEAK PREVENTION FILM

Fig. 6 B

AFTER HEATING TREATMENT

SMOOTHENED THROUGH MELTING




Fig. 7




Fig. 8




Fig. 9




Fig. 10

